Installation Instructions

Cineperm Permanently Tensioned Projection Screen by Draper

Caution

- 1 Read instructions through completely before proceeding.
- ③ Follow instructions carefully. Installation contrary to instructions invalidates warranty.
- ③ Bent or warped frames will affect surface flatness and image guality.
- ④ Screen should be square, and width should not vary from the center to the ends of the frame
- (1) When lifting assembled screen, do not lift at only one corner; lift at both corners. Lifting by one corner could result in damage to the screen frame, especially on large screens.
- [®] Screen should be installed level (using a carpenter's level).
- ⑦ Nothing should be fastened to screen frame or viewing surface.
- Is Be careful not to rip screen material when attaching surface to frame. The ideal temperature range for assembling this screen to prevent damaging the surface is 68°-78° F (20°-26° C). Assembling below
- recommended temperatures may damage surface and void warranty. If screen is to be flown (suspended), Truss Frame MUST be used.
- NOTE: Screen has been inspected and tested at factory prior to shipment.


Frame Assembly

Standard Frame (Do NOT Suspend)—

- 1 Lay out frame pieces on floor, by matching up color-coded tape near corners. Snaps should be facing up.
- ② Assemble frame (see Fig. 1). If necessary gently tap frame ends with a rubber mallet to make sure castings are fully seated.

Truss Frame-

- ① Unfold and lay out pieces on floor, by matching up color coded marks. Lock all hinges (see Fig. 1). Snaps should be facing up.
- ⁽²⁾ To increase frame rigidity, hinges on top and bottom sections have rivnuts marked with red and green. Insert a Handy Crank through the threadless rivnut (red) and tighten into the threaded rivnut (green).
- ③ Apply small sections marked "Stiffener Bars" to back of bottom frame section, using 8 Handy Cranks. These eliminate sag on large suspended frames. Failure to use all Handy Cranks may result in screen frame damage. Turn bottom frame section over so snaps face up.
- Repeat step 3 for top frame section.
- ⑤ Join top and bottom sections to Stage Left and Stage Right, using 2 Handy Cranks on each of the 4 corners. Match numbers on white labels. NOTE: No Handy Crank should protrude outside screen frame.
- (6) Attach surface (see "Surface Installation"), and suspend using appropriate materials (provided by others to meet specific installation requirements).




Frame Installation (Standard Frame)

Outside (Face) Mount-

- ① Drill mounting holes in frame (see Fig. 2).
- ② Mark wall and drill holes to correspond with those in the frame.
- ③ Enlarge holes in frame side furthest from wall to allow screw heads to pass through (see Fig. 2). Do not allow screw heads to remain outside the frame: overtightening could bend frame and affect screen flatness.

④ Attach frame to wall using appropriate fasteners for mounting surface (provided by others).

NOTE: Measure screen frame width at the top, bottom, and center; Make sure the frame is installed so the center width is same as the width at the top and bottom.



Inside (Jamb) Mount-

- ① Place frame assembly in opening to check for a snug fit. If frame is too large, opening may have to be enlarged. If frame is too small or does not sit square in the opening, shims and caulking may be required.
- ② Drill mounting holes in frame, and enlarge the first holes to allow screw heads to pass through (see Fig. 3). Do not allow screw heads to remain outside the frame: overtightening could bend frame and affect screen flatness.
- 3 Drill holes in jamb.
- (1) Attach frame using appropriate fasteners for mounting surface (provided by others).
- ⑤ Use caulk to ensure there is no light leakage around edges of frame.





Figure 3

Surface Installation

- ① Carefully remove surface from cardboard tube and unroll onto a clean cloth or paper.
- Engage snaps in each corner, then secure rest of screen snaps.
- ③ Stretch fabric across frame. Use extreme caution when attaching fabric. Overstretching or rough handling could cause the viewing surface to tear.



411 S. Pearl St., Spiceland, IN 47385 USA 265-987-7999 www.draperinc.com I fax 765-987-7142 Copyright © 2014 Draper Inc. Form Cineperm_Inst14-R Printed in U.S.A.

R

If you encounter any difficulties installing or servicing your Cineperm, call your dealer or Draper, Inc. in Spiceland, Indiana, 765-987-7999, or fax 765-987-7142.